


# Update Instructions

1. Unzip the file “Tornado V#.#.zip”.
2. Open “Tornado V#.#” folder.
3. Open folder “XLoader”, run XLoader.exe.
4. Connect USB cable to mainboard.
5. Locate firmware HEX file & select correct com port. (Pic Below)



6. Click “Upload” and wait for upload to complete.
7. Done.